


- NOTCH SENSITIVITY

- It is observed that the actual reduction in the endurance limit of a material due to stress concentration is less than the amount indicated by the theoretical stress concentration factor K_t . Therefore, two separate notations, K_t and K_f , are used for stress concentration factors. K_t is the theoretical stress concentration factor, as defined in previous sections, which is applicable to ideal materials that are homogeneous, isotropic and elastic. K_f is the fatigue stress concentration factor, which is defined as follows:

$$K_f = \frac{\text{Endurance limit of the notch free specimen}}{\text{Endurance limit of the notched specimen}}$$

- This factor K_f is applicable to actual materials and depends upon the grain size of the material. It is observed that there is a greater reduction in the endurance limit of fine-grained materials as compared to coarse-grained materials, due to stress concentration. Notch sensitivity is defined as the susceptibility of a material to succumb to the damaging effects of stress raising notches in fatigue loading. The notch sensitivity factor q is defined as


$$q = \frac{\text{Increase of actual stress over nominal stress}}{\text{Increase of theoretical stress over nominal stress}}$$

- Since σ_o = nominal stress as obtained by elementary
- equations

$$\therefore \begin{aligned} \text{actual stress} &= K_f \sigma_o \\ \text{theoretical stress} &= K_t \sigma_o \end{aligned}$$

increase of actual stress over nominal stress

$$= (K_f \sigma_o - \sigma_o)$$

increase of theoretical stress over nominal stress =

$$(K_t \sigma_o - \sigma_o)$$




Fig. 5.22 Notch Sensitivity Charts (for Reversed Bending and Reversed Axial Stresses)

$$q = \frac{(K_f \sigma_o - \sigma_o)}{(K_t \sigma_o - \sigma_o)}$$

or
$$q = \frac{(K_f - 1)}{(K_t - 1)} \quad (5.11)$$

The above equation can be rearranged in the following form:

$$K_f = 1 + q(K_t - 1) \quad (5.12)$$




Fig. 5.23 Notch Sensitivity Charts (for Reversed Torsional Shear Stresses)

The following conclusions are drawn with the help of Eq. (5.12).

- (i) When the material has no sensitivity to notches,

$$q = 0 \quad \text{and} \quad K_f = 1$$

- (ii) When the material is fully sensitive to notches,

$$q = 1 \quad \text{and} \quad K_f = K_t$$


Lecture Machine Design

• REVERSED STRESSES—DESIGN FOR FINITE AND INFINITE LIFE

- There are two types of problems in fatigue design—
- (i) components subjected to completely reversed stresses, and (ii) components subjected to fluctuating stresses.
- The design problems for completely reversed stresses are further divided into two groups—
- (i) design for infinite life, and
- (ii) design for finite life.
- Case I: When the component is to be designed for infinite life, the endurance limit becomes the criterion of failure. The amplitude stress induced in such components should be lower than the endurance limit in order to withstand the infinite number of cycles. Such components are designed with the help of the following equations:

$$\sigma_a = \frac{S_e}{(fs)} \quad (5.31)$$

$$\tau_a = \frac{S_{se}}{(fs)} \quad (5.32)$$



where (σ_a) and (τ_a) are stress amplitudes in the component and S_e and S_{se} are corrected endurance limits in reversed bending and torsion respectively.




Fig. 5.27 S-N Curve

- Case II: When the component is to be designed for finite life, the S–N curve as shown in Fig. 5.27 can be used. The curve is valid for steels. It consists of a straight line AB drawn from $(0.9 S_{ut})$ at 10^3 cycles to (S_e) at 10^6 cycles on a log-log paper.

Lecture Machine Design

- The design procedure for such problems is as follows:
- (i) Locate the point A with coordinates $[3, \log_{10}(0.9S_{ut})]$ since $\log_{10}(10^3) = 3$
- (ii) Locate the point B with coordinates $[6, \log_{10}(S_e)]$ since $\log_{10}(10^6) = 6$
- (iii) Join AB, which is used as a criterion of failure for finite-life problems
- (iv) Depending upon the life N of the component, draw a vertical line passing through $\log_{10}(N)$ on the abscissa. This line intersects AB at point F.
- (v) Draw a line FE parallel to the abscissa. The ordinate at the point E, i.e. $\log_{10}(S_f)$, gives the fatigue strength corresponding to N cycles. The value of the fatigue strength (S_f) obtained by the above procedure is used for the design calculations.



Lecture Machine Design

Example 5.3 A plate made of steel 20C8 ($S_{ut} = 440 \text{ N/mm}^2$) in hot rolled and normalised condition is shown in Fig. 5.28. It is subjected to a completely reversed axial load of 30 kN. The notch sensitivity factor q can be taken as 0.8 and the expected reliability is 90%. The size factor is 0.85. The factor of safety is 2. Determine the plate thickness for infinite life.




Fig. 5.28

Solution

Given $P = \pm 30 \text{ kN}$ $S_{ut} = 440 \text{ N/mm}^2$ $(fs) = 2$
 $R = 90\%$ $q = 0.8$ $K_b = 0.85$

Step I Endurance limit stress for plate

$$S'_e = 0.5 S_{ut} = 0.5(440) = 220 \text{ N/mm}^2$$

From Fig. 5.24 (hot rolled steel and $S_{ut} = 440 \text{ N/mm}^2$),

$$K_a = 0.67$$

$$K_b = 0.85$$

For 90% reliability,

$$K_c = 0.897$$

$$\frac{d}{w} = \frac{10}{50} = 0.2$$

From Fig. 5.2, $K_t = 2.51$

From Eq. (5.12),

$$K_f = 1 + q(K_t - 1) = 1 + 0.8(2.51 - 1) = 2.208$$

$$K_d = \frac{1}{K_f} = \frac{1}{2.208} = 0.4529$$

$$\begin{aligned} S_e &= K_a K_b K_c K_d S'_e \\ &= 0.67(0.85)(0.897)(0.4529)(220) \\ &= 50.9 \text{ N/mm}^2 \end{aligned}$$

For axial load, (Eq. 5.30)

$$(S_e)_a = 0.8 S_e = 0.8(50.9) = 40.72 \text{ N/mm}^2$$

Step II Permissible stress amplitude

$$\sigma_a = \frac{(S_e)_a}{(fs)} = \frac{40.72}{2} = 20.36 \text{ N/mm}^2 \quad (a)$$

Step III Plate thickness

$$\sigma_a = \frac{P}{(w-d)t} = \frac{(30)(10^3)}{(50-10)t} \text{ N/mm}^2 \quad (b)$$

From (a) and (b),

$$20.36 = \frac{(30)(10^3)}{(50-10)t}$$

$$\therefore t = 36.84 \text{ mm}$$

